1. Loop cable tie around bundle. Insert the tail into the buckle and pull tight by hand.

2. Slide the tail into the side entry and position the tool as shown. Position the tool against the base of the buckle.

3. Squeeze the handle to tighten tie to the desired tension.

4. Maintain final handle pressure and rotate cutter bar upward for cut off.

Note: XE9229 is a non-warranty item.